

Service Address	Utility Owned Lines	Privately Owned Service Lines	Basis of Street Side Material Classification	Basis of Property Side Material Classification	Notes of Basis of Material Classification
202 LIBERTY DR - W	Copper	Copper	Field inspection only	Field inspection only	
104 LIBERTY DR - W	Copper	Copper	Field inspection only	Field inspection only	
103 LIBERTY DR - W	Copper	Copper	Field inspection only	Field inspection only	
107 LIBERTY DR - W	Copper	Copper	Field inspection only	Field inspection only	
203 LIBERTY DR - W	Copper	Copper	Field inspection only	Field inspection only	
205 LIBERTY DR - W	Copper	Copper	Field inspection only	Field inspection only	
207 LIBERTY DR - W	Copper	Copper	Field inspection only	Field inspection only	
307 1ST AVE - N	Copper	Copper	Field inspection only	Field inspection only	
305 1ST AVE - N	Copper	Copper	Field inspection only	Field inspection only	
303 1ST AVE - N	Copper	Copper	Field inspection only	Field inspection only	
301 1ST AVE - N	Copper	Copper	Field inspection only	Field inspection only	
112 EATON CT	Copper	Copper	Field inspection only	Field inspection only	
110 EATON CT	Copper	Copper	Field inspection only	Field inspection only	
108 EATON CT	Copper	Copper	Field inspection only	Field inspection only	
106 EATON CT	Copper	Copper	Field inspection only	Field inspection only	
104 EATON CT	Copper	Copper	Field inspection only	Field inspection only	
102 EATON CT	Copper	Copper	Field inspection only	Field inspection only	
126 COLONIAL DR	Copper	Copper	Field inspection only	Field inspection only	
105 1ST AVE - N	Copper	Copper	Field inspection only	Field inspection only	
124 COLONIAL DR	Copper	Copper	Field inspection only	Field inspection only	
122 COLONIAL DR	Copper	Copper	Field inspection only	Field inspection only	
120 COLONIAL DR	Copper	Copper	Field inspection only	Field inspection only	
118 COLONIAL DR	Copper	Copper	Field inspection only	Field inspection only	
116 COLONIAL DR	Copper	Copper	Field inspection only	Field inspection only	
110 COLONIAL DR	Copper	Copper	Field inspection only	Field inspection only	
105 COLONIAL DR	Copper	Copper	Field inspection only	Field inspection only	
107 COLONIAL DR	Copper	Copper	Field inspection only	Field inspection only	
105 PARK LANE	Copper	Copper	Field inspection only	Field inspection only	
312 MAIN ST - W	Copper	Copper	Field inspection only	Field inspection only	
314 MAIN ST - W	Copper	Copper	Field inspection only	Field inspection only	
316 MAIN ST - W	Copper	Copper	Field inspection only	Field inspection only	
318 MAIN ST - W	Copper	Copper	Field inspection only	Field inspection only	
320 MAIN ST - W	Copper	Copper	Field inspection only	Field inspection only	
310 SIMON DR	Copper	Copper	Field inspection only	Field inspection only	
310 SIMON DR	Copper	Copper	Field inspection only	Field inspection only	
320 SIMON DR	Copper	Copper	Field inspection only	Field inspection only	
321 SIMON DR	Copper	Copper	Field inspection only	Field inspection only	
315 COLONIAL LN	Plastic	Plastic	Field inspection only	Field inspection only	
608 1ST AVE - N	Copper	Copper	Field inspection only	Field inspection only	
100 PARK LANE	Copper	Copper	Field inspection only	Field inspection only	
510 4TH AVE - S	Copper	Plastic	Field inspection only	Field inspection only	
600 4TH AVE - S	Copper	Copper	Field inspection only	Field inspection only	
600 4TH AVE - S	Copper	Copper	Field inspection only	Field inspection only	
600 4TH AVE - S	Copper	Copper	Field inspection only	Field inspection only	
600 4TH AVE - S DORM	Copper	Copper	Field inspection only	Field inspection only	

Service Address	Utility Owned Lines	Privately Owned Service Lines	Basis of Street Side Material Classification	Basis of Property Side Material Classification	Notes of Basis of Material Classification
SAINT NAZIANZ MOBILE HOME COURT 1 MAPLE TERRACE	Copper	Copper	Field inspection only	Other - describe in notes	Service line connects to a mobile home park as a single customer; material of the service lines to each of the trailers was not documented
Lot 1	Transite	Copper	Field inspection only	Field inspection only	
Lot 2	Transite	Copper	Field inspection only	Field inspection only	
Lot 3	Transite	Copper	Field inspection only	Field inspection only	
Lot 4	Transite	Copper	Field inspection only	Field inspection only	
Lot 5	Transite	Copper	Field inspection only	Field inspection only	
Lot 6	Transite	Copper	Field inspection only	Field inspection only	Scheduled to be occupied in 2025
Lot 7	Transite	Copper	Field inspection only	Field inspection only	
Lot 8	Transite	Copper	Field inspection only	Field inspection only	Scheduled to be occupied in 2025
Lot 9	Transite	Copper	Field inspection only	Field inspection only	
Lot 10	Transite	Copper	Field inspection only	Field inspection only	
Lot 11	Transite	Copper	Field inspection only	Field inspection only	Scheduled to be occupied in 2025
Lot 12	Transite	Copper	Field inspection only	Field inspection only	
Lot 13	Transite	Copper	Field inspection only	Field inspection only	
Lot 15	Transite	Copper	Field inspection only	Field inspection only	
Lot 16	Transite	Copper	Field inspection only	Field inspection only	
Lot 17	Transite	Copper	Field inspection only	Field inspection only	
Lot 18	Transite	Copper	Field inspection only	Field inspection only	
Lot 19	Transite	Copper	Field inspection only	Field inspection only	
Lot 21	Transite	Copper	Field inspection only	Field inspection only	
Lot 23	Transite	Copper	Field inspection only	Field inspection only	
Lot 25	Transite	Copper	Field inspection only	Field inspection only	
Lot 27	Transite	Copper	Field inspection only	Field inspection only	
Lot 29	Transite	Copper	Field inspection only	Field inspection only	
Lot 30	Transite	Copper	Field inspection only	Field inspection only	
Lot 31	Transite	Copper	Field inspection only	Field inspection only	
Lot 32	Transite	Copper	Field inspection only	Field inspection only	Scheduled to be occupied in 2025
Lot 33	Transite	Copper	Field inspection only	Field inspection only	Scheduled to be occupied in 2025
Lot 34	Transite	Copper	Field inspection only	Field inspection only	
Lot 35	Transite	Copper	Field inspection only	Field inspection only	
Lot 36	Transite	Copper	Field inspection only	Field inspection only	Scheduled to be occupied in 2025
Lot 38	Transite	Copper	Field inspection only	Field inspection only	Scheduled to be occupied in 2025
Lot 39	Transite	Copper	Field inspection only	Field inspection only	
Lot 40	Transite	Copper	Field inspection only	Field inspection only	
Lot 49	Transite	Copper	Field inspection only	Field inspection only	
Lot 50	Transite	Copper	Field inspection only	Field inspection only	
Lot 52	Transite	Copper	Field inspection only	Field inspection only	
Lot 53	Transite	Copper	Field inspection only	Field inspection only	
Lot 55	Transite	Copper	Field inspection only	Field inspection only	
Lot 59	Transite	Copper	Field inspection only	Field inspection only	
Lot 60	Transite	Copper	Field inspection only	Field inspection only	
Lot 71	Transite	Copper	Field inspection only	Field inspection only	
Lot 73	Transite	Copper	Field inspection only	Field inspection only	
Lot 75	Transite	Copper	Field inspection only	Field inspection only	
Lot 77	Transite	Copper	Field inspection only	Field inspection only	
Lot 79	Transite	Copper	Field inspection only	Field inspection only	